

Gurmeet Singh Bhuye



B.E.(Structural), D.B.M., Prov.Mem. CBRI
Licenced Engineer, Designer & Contractor & Developer

Ph.No.(Res.) 240778.
(Off.) 240278.
7276837878, 9422835755.
Lic.NoMC/01.

E mail - gurmeetsinghbhuye@gmail.com

Office :- BTS LAYOUT PLOT No.-60/A, SHIVAJI WARD, BALLARPUR -442701 (M.S.)

Ref.No.:-

Date :- 25/08/2018

STRUCTURAL SOUNDNESS CERTIFICATE.

1. NAME OF SCHOOL :- STELLA MARIS SCHOOL , BAMANWADA,TAL.:-RAJURA.
2. NAME OF SOCIETY:-SOCIETY OF THE DAUGHTERS OF MARY ,CHANDA ,
DIST.:- CHANDRAPUR.
3. ENROLMENT No.- MAHARASHTRA 363/92 (CHANDRAPUR)
4. AFFILIATION No. :- 1130246.
5. LOCATION :-_S.Nos.:- 185, 189/2 , BAMANWADA , CHUNALA
P.O.- RAJURA , Dist:- Chandrapur ,MAHARASHTRA- 442905
Google Map – 19.783949,79.379453,18
6. PURPOSE :- BUILDING SAFETY CERTIFICATE
7. ISSUED ON DATE :- 25/08/2018
8. BUILDING DETAILS :- The building to be certified is a main school building in front and is a triple storeyed with administrative block and classrooms etc. in the same premises , facing "NORTH", and the entrance from main road is also from "NORTH".

some of the details are as follow-

- a. BUILDING --- (as shown in the google satellite print) , is the old building , a three storeyed framed structure with RCC column based footing ,plinth beams , lintel beams,slab beams , RCC slabs , RCC staircases , brickwalls plastered and colour washed all over , being build in the year 1997-98 ,1998-99 and 1999-2000 , now completely being used as an Institutional building ,photographs are also attached .

OPINION/OBSERVATION:- This building shows no signs or impressions of any type of failure ,and is well maintained , could be used further for the same purpose for as many 20 to 25 years more.

Contd. On page 2.

CONCLUSION :-

THE BUILDING IS STRUCTURALLY SOUND ENOUGH FOR THE USE ALREADY
BEING IN FOR THE FUTURE AS MENTIONED.



GURMEET SINGH BHUYE.

BALLARPUR

GURMEET SINGH BHUYE

Dt. - 25/08/2018

LICENCED PLANNER,
DESIGNER, ESTIMATOR VALUER
& BUILDING DEVELOPER
Mob. 9422835755 / 7276837878